

## **Addition program record data to CF-Card Project installation report for IEMT**

Made for: isuzu engine manufacturing co.( Thailand ) Ltd.  
By : TOMAS TECH CO.,LTD.

---



# **TOMAS TECH**

**TOMAS TECH CO.,LTD.**

7/1 (3C) Udomsuk 46 Alley, Khwaeng Bang Na, Khet Bang Na, Bangkok 10260 Thailand  
Tel :+66-98-271-9741 E-mail : info@tomastc.com

## Installation report 20/01/2024 ( MC30OP80 )

Installation Ethernet-Hub and wiring power SR-X300





## Installation report 20/01/2024 ( MC30OP80 )

Installation Ethernet-Hub and wiring power SR-X300





## Installation report 20/01/2024 ( MC30OP80 )

Installation Ethernet-Hub and wiring power SR-X300



# Installation report 20/01/2024 ( MC30OP80 )

Addition program record data to CF-Card

## Definition of each information

Column format data

1	2	3	4	5	6	7	8
211101	084500	SN00000001	30	80	1	1	1
211101	084501	SN00000002	30	80	2	2	2
211101	084502	SN00000003	30	80	1	3	1
211101	084503	SN00000004	30	80	1	1	2
211101	084504	SN00000005	30	80	1	1	2
211101	084505	SN00000006	30	80	1	1	1
211101	084506	SN00000007	30	80	1	1	1
211101	084507	SN00000008	30	80	1	1	1
211101	084508	SN00000009	30	80	1	1	1
211101	084509	SN00000010	30	80	1	1	1

## Specification

1. Date [ 231101 : 23 ( Year ) 11 ( Month ) 01 ( Day ) ]
2. Time [ 084500 : 08 ( Hr. ) 45 ( Min. ) 00 ( Sec. ) ]
3. Serial Number [ Ref. Part Number ]
4. Line MC [ 30 : Line MC30 ]
5. OP [ 80 : OP-80 ]
6. Mode [ 1 : Auto , 2 : Manual ]
7. Event definition [ 01: Start, 02: Load, 03: Finish process, 05: unload, 08: alarm, 09: cycle stop
8. Result 1:OK 2:NG

COPYRIGHT © TOMAS TECH CORPORATION. ALL RIGHTS RESERVED.

6

340120 - Notepad


File Edit Format View Help

```
240120 154700 ER 30 80 01 03 01
240120 154832 ER 30 80 01 05 01
240120 154836 30 80 01 02 01
240120 154856 ER 30 80 01 03 01
240120 155028 ER 30 80 01 05 01
240120 155031 30 80 01 02 01
240120 155051 ER 30 80 01 03 01
240120 155224 ER 30 80 01 05 01
240120 155227 30 80 01 02 01
240120 155247 ER 30 80 01 03 01
240120 155536 ER 30 80 01 05 01
240120 155540 30 80 01 02 01
240120 155600 ER 30 80 01 03 01
240120 155734 ER 30 80 01 05 01
240120 155738 30 80 01 02 01
240120 155758 ER 30 80 01 03 01
240120 155932 ER 30 80 01 05 01
240120 155936 30 80 01 02 01
240120 155955 ER 30 80 01 03 01
240120 160129 ER 30 80 01 05 01
240120 160133 30 80 01 02 01
240120 160153 ER 30 80 01 03 01
240120 160327 ER 30 80 01 05 01
240120 160331 30 80 01 02 01
240120 160351 ER 30 80 01 03 01
240120 160645 ER 30 80 01 05 01
240120 160649 30 80 01 02 01
240120 160709 ER 30 80 01 03 01
240120 160917 ER 30 80 01 05 01
240120 160920 30 80 01 02 01
240120 160940 ER 30 80 01 03 01
240120 161137 ER 30 80 01 05 01
240120 161141 30 80 01 02 01
240120 161200 ER 30 80 01 03 01
```

## Result after addition program

# Installation report 20/01/2024 ( MC30OP80 )

Problem read serial part error



*The problem of reading Serial part error is caused by the SR-X300 camera's reading being unable to read. Due to problems with tuning We'll be in touch with Keyence to help with tuning again next week.*