

Thai Nippon foods Co.,Ltd. - Problem-Bug #659

Parent project # 551 (Closed): [PJ230043]IoT Equipment for machine operation project

water flow sensor error

11 Jul 2024 20:22 - Nattapol Poeam

<b>Status:</b>	Closed	<b>Start date:</b>	11 Jul 2024
<b>Priority:</b>	Normal	<b>Due date:</b>	31 Jul 2024
<b>Assignee:</b>	Konlawat Saechee	<b>% Done:</b>	100%
<b>Category:</b>		<b>Estimated time:</b>	60.00 hours
<b>Target version:</b>		<b>Spent time:</b>	52.00 hours
<b>Finish date:</b>	01 Oct 2024	<b>DB skills:</b>	Not using
<b>Programming skills:</b>	No development	<b>OS skills:</b>	Not using
<b>Description</b>			
- Check problem of sensor			
- Change device			

History

#1 - 11 Jul 2024 20:23 - Nattapol Poeam

08/07/2024  
Change water flow sensor serial no.20  
Next action  
Return flow to supplier 14/07/2024

#2 - 11 Jul 2024 20:47 - Nattapol Poeam

- Status changed from New to In Progress

#3 - 28 Nov 2024 16:56 - Konlawat Saechee

- Status changed from In Progress to Confirmation request  
- % Done changed from 0 to 100  
- Finish date set to 01 Oct 2024

#4 - 24 Dec 2024 20:10 - Kittisak Isarapongporn

- Status changed from Confirmation request to Close request

#5 - 24 Dec 2024 22:39 - Ryo Nozaki

- Status changed from Close request to Closed