

## Issues

Estimated time: 64.0 Spent time: 0.0

#	Project	Tracker	Status	Priority	Subject	Assignee	Total estimated time	Total spent time	Updated
7010	DAIFUKU (THAILAND) LTD.	Project progress work	Closed	Normal	[Installation&On-site support] Add alarm No. 27 Image error (case 1 picture)	Sermsak Prowee	8.00	0.00	20 Mar 2026 11:21
6720	DAIFUKU (THAILAND) LTD.	Project progress work	Closed	Normal	[Installation&On-site support] Onsite add PLC cross-check function to all station. (total 4 stations)	Sermsak Prowee	8.00	0.00	23 Feb 2026 14:03
4457	DAIFUKU (THAILAND) LTD.	Project progress work	Closed	Normal	[Installation&On-site support] Report preventive maintenance summary	Phatthadon Inthachot	40.00	0.00	18 Mar 2026 08:41
4456	DAIFUKU (THAILAND) LTD.	Project progress work	Closed	Normal	[Installaton&On-site support] Preventive mantinance	Phatthadon Inthachot	8.00	0.00	18 Mar 2026 08:41