

DAIFUKU (THAILAND) LTD. - Project progress work #7010

Parent project # 4451 (Closed): [PJ260005] Camera system Preventive mantianace for P04

Project progress work # 4455 (Closed): [Installation&On-site support]

[Installation&On-site support] Add alarm No. 27 Image error (case 1 picture)

20 Mar 2026 11:21 - Waraporn Promsopa

Status:	Closed	Start date:	16 Mar 2026
Priority:	Normal	Due date:	16 Mar 2026
Assignee:	Sermsak Prowee	% Done:	100%
Category:		Estimated time:	8.00 hours
Target version:		Spent time:	0.00 hour
Finish date:	16 Mar 2026	DB skills:	MS SQL Server
Programming skills:	Web/PHP	OS skills:	Windows server
Description			

History

#1 - 20 Mar 2026 11:21 - Waraporn Promsopa

- Status changed from New to Closed