

MITSUBISHI ELECTRIC CONSUMER PRODUCTS (THAILAND) CO., LTD. - Parent project #8693

[PJ260124] Inspection Motor Lifter 6 set for A,B,G Line

29 Jun 2026 16:47 - Waraporn Promsopa

Status:	In Progress	Start date:	
Priority:	Normal	Due date:	
Assignee:	Warit Chunlaka	Spent time:	0.00 hour
Description			
Subtasks:			
Project progress work # 8694: [Requirement definition]			New
Project progress work # 8695: [Internal Design]			New
Project progress work # 8696: [Coding]			New
Project progress work # 8697: [Installation&On-site support]			New

History

#1 - 29 Jun 2026 16:49 - Waraporn Promsopa

1 Inspection Report

1-1 Inspection Fee for Motor Lifter Qty 1 job

Total 6 Machine Inspection ,Inscope as list as below

» Lifter General : A Line ,B Line and G Line < Mechanical and Electrical >

» Lifter Robot : A Line ,B Line and G Line < Mechanical and Electrical >

Note)

These Motor Lifter never inspection by Hirata or Tomas Tech before

We have to spend a time more than normal and have to site survey for prepare the inspection sheet format

Remark :

Condition : This Quotation for "Inspection Fee and Document Report" Only.

This Quotation is not included any new parts or modification.

Lead time : 30days for "Inspection reports" after complete inspection all lifter.

Payment :

50% DP upon PO Credit 7days

50% after delivery "Inspection reports" to MCP site Credit 30days